

ANNUAL VEHICLE INSPECTION REPORT

| VEHICLE HISTORY RECORD | |
|----------------------------------------------------|-------------------|
| REPORT NUMBER | FLEET UNIT NUMBER |
| | 162 |
| DATE 3/1/23 | |

| | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| MOTOR CARRIER OPERATOR GGG Specialized Carriers | INSPECTOR'S NAME (PRINT OR TYPE) Mike Gajda |
| ADDRESS 582 W 194th Apollo Dr | THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES |
| CITY, STATE, ZIP CODE Muskego WI 53150 | VEHICLE IDENTIFICATION (VIN) AND COMPLETE <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTH 1T K5024291M 115408 |
| VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> (OTHER) | INSPECTION AGENCY/LOCATION (OPTIONAL) |

VEHICLE COMPONENTS INSPECTED

| OK | NEEDS REPAIR | REPAIRED DATE | ITEM | OK | NEEDS REPAIR | REPAIRED DATE | ITEM |
|----|--------------|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|--------------|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | 1. BRAKE SYSTEM | | | | 4. FUEL SYSTEM |
| X | | | a. Service Brakes | X | | | a. Visible leak |
| X | | | b. Parking Brake System | X | | | b. Fuel tank filler cap missing |
| X | | | c. Brake Drums or Rotors | X | | | c. Fuel tank securely attached |
| X | | | d. Brake Hose | | | | 5. LIGHTING DEVICES |
| X | | | e. Brake Tubing | | | | All lighting devices and reflectors required by Section 393 shall be operable. |
| X | | | f. Low Pressure Warning Device | X | | | 6. SAFE LOADING |
| X | | | g. Tractor Protection Valve | | | | a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway. |
| X | | | h. Air Compressor | X | | | b. Protection against shifting cargo |
| X | | | i. Electric Brakes | | | | 7. STEERING MECHANISM |
| X | | | j. Hydraulic Brakes | | | | a. Steering Wheel Free Play |
| X | | | k. Vacuum Systems | | | | b. Steering Column |
| | | | 2. COUPLING DEVICES | | | | c. Front Axle Beam and All Steering Components Other Than Steering Column |
| X | | | a. Fifth Wheels | X | | | d. Steering Gear Box |
| X | | | b. Pintle Hooks | | | | e. Pitman Arm |
| X | | | c. Drawbar/Towbar Eye | | | | f. Power Steering |
| X | | | d. Drawbar/Towbar Tongue | | | | g. Ball and Socket Joints |
| X | | | e. Safety Devices | | | | h. Tie Rods and Drag Links |
| X | | | f. Saddle-Mounts | | | | i. Nuts |
| | | | 3. EXHAUST SYSTEM | | | | j. Steering System |
| X | | | a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment. | | | | 8. SUSPENSION |
| X | | | b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3). | | | | a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position. |
| X | | | c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle. | | | | b. Spring Assembly |
| | | | | | | | c. Torque, Radius or Tracking Components. |
| | | | | | | | 9. FRAME |
| | | | | | | | a. Frame Members |
| | | | | | | | b. Tire and Wheel Clearance |
| | | | | | | | c. Adjustable Axle Assemblies (Sliding Subframes) |
| | | | | | | | 10. TIRES |
| | | | | | | | a. Tires on any steering axle of a power unit. |
| | | | | | | | b. All other tires. |
| | | | | | | | 11. WHEELS AND RIMS |
| | | | | | | | a. Lock or Side Ring |
| | | | | | | | b. Wheels and Rims |
| | | | | | | | c. Fasteners |
| | | | | | | | d. Welds |
| | | | | | | | 12. WINDSHIELD GLAZING |
| | | | | | | | Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions) |
| | | | | | | | 13. WINDSHIELD WIPERS |
| | | | | | | | Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective. |
| | | | | | | | List any other condition which might prevent safe operation of this vehicle. |

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: OK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT ACCORDANCE WITH 49 CFR 396.