

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	75
DATE	
11/4/22	

MOTOR CARRIER OPERATOR
 666 Specialized Carriers

ADDRESS
 582 W 19480 Apollo Dr

CITY, STATE, ZIP CODE
 Muskegon WI 53150

VEHICLE TYPE TRACTOR TRAILER TRUCK
 (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)
 Mike Gajnic

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.
 YES

VEHICLE IDENTIFICATION (VIN) AND COMPLETE LIC. PLATE NO. VIN
 33521027

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
X			1. BRAKE SYSTEM
X			a. Service Brakes
X			b. Parking Brake System
X			c. Brake Drums or Rotors
X			d. Brake Hose
X			e. Brake Tubing
X			f. Low Pressure Warning Device
X			g. Tractor Protection Valve
X			h. Air Compressor
X			i. Electric Brakes
X			j. Hydraulic Brakes
X			k. Vacuum Systems
X			2. COUPLING DEVICES
X			a. Fifth Wheels
X			b. Pintle Hooks
X			c. Drawbar/Towbar Eye
X			d. Drawbar/Towbar Tongue
X			e. Safety Devices
X			f. Saddle-Mounts
X			3. EXHAUST SYSTEM
X			a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment.
X			b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3).
X			c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle.
X			4. FUEL SYSTEM
X			a. Visible leak
X			b. Fuel tank filler cap missing
X			c. Fuel tank securely attached
X			5. LIGHTING DEVICES
X			All lighting devices and reflectors required by Section 393 shall be operable.
X			6. SAFE LOADING
X			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
X			b. Protection against shifting cargo
X			7. STEERING MECHANISM
X			a. Steering Wheel Free Play
X			b. Steering Column
X			c. Front Axle Beam and All Steering Components Other Than Steering Column
X			d. Steering Gear Box
X			e. Pitman Arm
X			f. Power Steering
X			g. Ball and Socket Joints
X			h. Tie Rods and Drag Links
X			i. Nuts
X			j. Steering System
X			8. SUSPENSION
X			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
X			b. Spring Assembly
X			c. Torque, Radius or Tracking Components.
X			9. FRAME
X			a. Frame Members
X			b. Tire and Wheel Clear Assemblies (Sliding Subframes)
X			10. TIRES
X			a. Tires on any steering of a power unit.
X			b. All other tires.
X			11. WHEELS AND RIMS
X			a. Lock or Side Ring
X			b. Wheels and Rims
X			c. Fasteners
X			d. Welds
X			12. WINDSHIELD GLAZING
X			Requirements and exceptions as stated pertaining to any crack, discoloration or visior reducing matter (reference 393.60 for exceptions)
X			13. WINDSHIELD WIPERS
X			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
X			List any other condition which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: OK, NEEDS REPAIR, IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT ACCORDANCE WITH 49 CFR 396.